

VEER SURENDRA SAI UNIVERSITY OF TECHNOLOGY, BURLA

Department of Civil Engineering

(Formerly University College of Engineering, Burla, ESTD:1956)

P.O. Engineering College
Burla, PIN-768 018
Dist:Sambalpur, Odisha, (India)
www.vssut.ac.in



Phone No : 91-663-2430591 (O)
Fax No. : 91-663-2430204
PAN No- AAAGV0318K
GSTIN- 21AAAGV0318K1ZJ

No. VSSUT/ Civil/ 875

Date: 11/05/2022

From
Head, Department of Civil Engineering
VSS University of Technology, Burla

To,
The Principal
Kendriya Vidyalaya No – I,
Ordinance Factory, Badmal, Bolangir

Sub:- Safety certificate of the Kendriya Vidyalaya No – I school building at Ordinance Factory, Badmal, Bolangir

Ref: No- Your Letter No-F.150346/1155/KVOFBL/2021-2022/92, dt-19/04/2022

Dear Sir,

This has reference to your letter no. F.150346/1155/KVOFBL/2021-2022/92 dated 19/04/2022 on the above mentioned subject. You had requested us to visit the above mentioned school for visual inspection and to give report. Experts from civil engineering department had visited your school at the above mentioned address on 01.05.2022 and inspected the entire building.

Based on the visual observations, visual symptoms and manifestations shown by the building and the data collected from site, it is of the opinion that the said school building is structurally sound and that its stability will not be endangered by their use for which the building is intended.

Thanking you,

Sincerely yours

Head of the Department
Civil Engineering Department

HEAD
Department of Civil Engineering
VSSUT, Burla